



2. RESISTORS ARE MEASURED IN OHMS.
 1. CAPACITORS ARE MEASURED IN FARADS.
 NOTES—UNLESS OTHERWISE SPECIFIED:

UNLESS OTHERWISE SPECIFIED, TOLERANCES ARE: RESISTORS: 1% (R1-R100) CAPACITORS: 5% (C1-C100)		DRAWN BY: N. J. ... CHECKED: ... ENGINEER: O. ... APPROVED: ... DATE: 3-23-88	ATARI CORPORATION TITLE: SCHEMATIC DIAGRAM MEGAFILE 60 (RLL) SIZE: DRAWING NO. D 103166 SCALE: NONE SHEET 1 OF 1
APPLICATION: MEGAFILE 60 (RLL)		APPROVED: ... DATE: ...	NEXT ASSY: ... ORIGINAL MODEL: ... FINISH: ...